




Tenmet

TENMET 800 CALIBRATION 200 daN

SE Viktigt! Vid kalibrering, säkerställ att kalibreringsplåten ligger mitt under mäträullen vid kalibreringsmätning.

DE Wichtig! Achten Sie beim Kalibrieren darauf, dass das Kalibrierblech während der Kalibriermessung mittig unter der Messrolle positioniert ist.

EN Important! When calibrating, ensure that the calibration plate is positioned centrally under the measuring roller during calibration measurement.



5

